DSS Touch - Release Notes Rev 5

DSS Touch v5.3

New features

Version 5.3 includes the following changes:

- Finnish language support
- Norwegian language support

Known limitations

The following limitations in DSS Touch v5.3 are known:

- The DSS upgrade engine is unable to upgrade DSS Touch over RS-485 (USB connection is required).

Compatibility

DSS Touch v5.3 is compatible with the following program/firmware versions:

- Sentrion – DSS Touch v5.3 requires Sentrion v3.7.0 or later.
- Sentrion Manager – DSS Touch v5.3 requires Sentrion Manager v3.2.0 or later.

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se

DSS Touch - Release Notes Rev 5

DSS Touch v5.2

New features

Version 5.2 includes the following changes:

- The area selection presentation is now configurable, e.g. if available areas are preselected or not.

Corrections

Version 5.2 includes the following corrections:

- English is now used as a fallback if the selected language is not supported
- DSS Touch could sometimes freeze when making configuration changes
- Improved handling of login with many areas
- Improved handling of MIFARE Ultralight

Known limitations

The following limitations in DSS Touch v5.2 are known:

- The DSS upgrade engine is unable to upgrade DSS Touch over RS-485 (USB connection is required).

Compatibility

DSS Touch v5.2 is compatible with the following program/firmware versions:

- Sentrion – DSS Touch v5.2 requires Sentrion v3.7.0 or later.
- Sentrion Manager – DSS Touch v5.2 requires Sentrion Manager v3.2.0 or later.

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se

DSS Touch - Release Notes Rev 5

DSS Touch v5.1

New features

Version 5.1 includes the following changes:

- The attention required indication sound can now be disabled
- Added support for downloading configuration files over RS-485

Corrections

Version 5.1 includes the following corrections:

- Tamper was not correctly reported after a communication error

Known limitations

The following limitations in DSS Touch v5.1 are known:

- The DSS upgrade engine is unable to upgrade DSS Touch over RS-485 (USB connection is required).

Compatibility

DSS Touch v5.1 is compatible with the following program/firmware versions:

- Sentrion – DSS Touch v5.1 requires Sentrion v3.7.0 or later.
- Sentrion Manager – DSS Touch v5.1 requires Sentrion Manager v3.2.0 or later.

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se

DSS Touch - Release Notes **Rev 5**

DSS Touch v5.0

New features

Version 5.0 includes the following changes:

- Handshake is now required when communicating with the controller
- Units can now be locked to different SKU's during manufacturing

Known limitations

The following limitations in DSS Touch v5.0 are known:

- The DSS upgrade engine is unable to upgrade DSS Touch over RS-485 (USB connection is required).

Compatibility

DSS Touch v5.0 is compatible with the following program/firmware versions:

- Sentrion – DSS Touch v5.0 requires Sentrion v3.7.0 or later.
- Sentrion Manager – DSS Touch v5.0 requires Sentrion Manager v3.2.0 or later.

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se

DSS Touch - Release Notes Rev 5

DSS Touch v4.6

New features

Version 4.6 includes the following changes:

- Text now scrolls if an object name is longer than the screen width
- Optimizations for faster login and quicker loading of areas and sections
- Faster setting procedure when many sections or areas are used. Optimizations are primarily implemented in Sentrion version 4.2.1.

Corrections

Version 4.6 includes the following corrections:

- Fixes for various “graphical” crashes and restarts.
- Fix for incorrect logouts.

Known limitations

The following limitations in DSS Touch v4.6 are known:

- The DSS upgrade engine is unable to upgrade DSS Touch over RS-485 (USB connection is required).

Compatibility

DSS Touch v4.6 is compatible with the following program/firmware versions:

- Sentrion – DSS Touch v4.6 requires Sentrion v3.7.0 or later.
- Sentrion Manager – DSS Touch v4.6 requires Sentrion Manager v3.2.0 or later.

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se

DSS Touch - Release Notes Rev 5

DSS Touch v4.5

Corrections

Version 4.5 includes the following corrections:

- Fix for an issue where the control panel stopped reading cards if configured to read encrypted MIFARE Classic cards.

Known limitations

The following limitations in DSS Touch v4.5 are known:

- The DSS upgrade engine is unable to upgrade DSS Touch over RS-485 (USB connection is required).

Compatibility

DSS Touch v4.5 is compatible with the following program/firmware versions:

- Sentrion – DSS Touch v4.5 requires Sentrion v3.7.0 or later.
- Sentrion Manager – DSS Touch v4.5 requires Sentrion Manager v3.2.0 or later.

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se

DSS Touch - Release Notes Rev 5

DSS Touch v4.4

New features

Version 4.4 includes the following changes:

- Build date for current firmware is now reported

Corrections

Version 4.4 includes the following corrections:

- Reading DESFire cards could result in sporadic communication errors
- Sending long messages could result in communication errors
- Configuration of volume and brightness did not work
- Resuming from screensaver mode could result in bluescreen

Known limitations

The following limitations in DSS Touch v4.4 are known:

- The DSS upgrade engine is unable to upgrade DSS Touch over RS-485 (USB connection is required).

Compatibility

DSS Touch v4.4 is compatible with the following program/firmware versions:

- Sentrion – DSS Touch v4.4 requires Sentrion v3.7.0 or later.
- Sentrion Manager – DSS Touch v4.4 requires Sentrion Manager v3.2.0 or later.

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se

DSS Touch - Release Notes **Rev 5**

DSS Touch v4.3

New features

Version 4.3 includes the following corrections:

- Optimizations in the communication with Sentrion
- Recalibration of volume settings

Known limitations

The following limitations in DSS Touch v4.3 are known:

- The DSS upgrade engine is unable to upgrade DSS Touch over RS-485 (USB connection is required).

Compatibility

DSS Touch v4.3 is compatible with the following program/firmware versions:

- Sentrion – DSS Touch v4.3 requires Sentrion v3.7.0 or later.
- Sentrion Manager – DSS Touch v4.3 requires Sentrion Manager v3.2.0 or later.

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se