DSS mk2 Firmware v3 - Release Notes Rev 5

Version 3.6.10 May 3, 2024

- Fix for issue when using a single OSDP lock

Version 3.5.2 Jan 5, 2022

- Ignore card data and keypresses from card readers for a short period after connecting
- Added support for OSDP LED control setting
- Added filtering of allowed SetOutputs patterns
- Additional bug fixes

Version 3.4.1 Jun 25, 2021

- Added MUX-TCT mode
- Pacom 8707: indication fixes
- DSS DOOR, MUX: fix DC1 mode
- Safetron lock: fix inputs status

Version 3.3.6 Dec 16, 2020

- Added support for OSDPv2 connected lock by Safetron
- DSS IO21: fix for tamper indicator
- Pacom 8707: enhanced indication fixes
- Pacom 8707: added support for firmware download
- OSDP: minor protocol fixes

Version 3.2.5 Aug 18, 2019

- DSS IO82: fix for 12V output not working in 3.1 on certain card revisions
- Pacom 8707: added support for enhanced indications

Version 3.1.6 Jan 25, 2019

- Added support for OSDPv2 (secure channel)
- Added support for Pacom reader config push
- MUX: fix for Gari device under MUX

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se

Version 3.0.22 Mar 26, 2018

- Requires handshake to initiate communication
- MUX: fixes handling of "hardware replaced" function for devices under MUX

TLab West AB
Flöjelbergsgatan 18, 431 37 Mölndal
www.tlabwest.se
Technical support: +46 (0)31-830088
Mail: sentrion-support@tlabwest.se